



2012 Polaris 600R IQ Team Tip #2

We have heard a few reports that one or both of the rear torque arm wheel spacers (Polaris part no. 5134706) were not installed during the assembly process. Running your vehicle without this spacer will potentially damage the rear suspension. Please verify the installation of both spacers on the rear torque arm. If missing, please contact Brad Seavers at the Polaris Race Department, (715)-355-3008.





Wheel Spacer, 5134706